SEC. 4 T.4N.-R.4E.


Hopkins "A" Ditch
1
2
Hopkins and Mole Ditch
David Errol & Glenn D. Eddington.
55.8 Ac.
3
2000' W of E¼ Cor. Sec. 4
Hopkins Spring
Hopkins "B" Ditch
2445' N & 165' W of SW Cor Sec. 4-T4N-R
1650' N & 890' W of SW. Cor.
"Mole"
Rating Flume
H.B. Crouch & Henry Mole
31 Ac.
4
400' N & 1780' W of SE Cor.
Crouden Irrigation Ditch No.2