
T33S-R2W
-Sec 28-27
H-3
27
5.4Ac.
Cult. Not irrig. 1922
49.4Ac.
Brush
Cult. Not irrig. 1922
103.5Ac.
Application #2836
Certificate #350
Claims 428.5Ac.
Cult
Not irrig. 1922
37.5Ac.
Cult. Not irrig. 1922
102.1Ac.
171
36.6Ac.
Not irrig. 1922.
11.1Ac.
Not irrig. 1922
Not irrig. 1922
0.3Ac.
Past.
184
13.2Ac.
Past.
Brush
183
Past
10.4
Past.
15.3Ac.
15.8Ac.
Tim.
52.2Ac.
Timothy
Horse Creek
Twitchell Bros.
Brunson Ditch No 3
Tim.
6.5Ac.
10.8Ac.
181
183
Not irrigated for 10 years.
Ranch Creek
3.4Ac.
182
0.5Ac.
Grain
Brunson Ditch No 1
5.5Ac. Pasturage
181
Alfalfa
24.4Ac.
W.W. Steed
Pasture 4.4Ac.
1.2Ac.
Dry Grain
16.7Ac.
Past.
6.3Ac.
180
Steed Ditch No 2
Steed Ditch
Henderson Canal
This canal not incorporated. All water rights covered by various private applications. Canal not used in 1922
Note: All irrigators from Horse, Birch & Ranch Creeks are incorporated as the Horse Creek Irrigation Co.
W.J. Henderson, Pres.
Perry Shirtz, Secy.
Owners under Henderson Canal:
Luther Morrill.
John Stoker
Gilbert R. Beebe
J.C. Taylor
Jas. Ackerman
Mrs. Nettie Ackerman
C.L. Elder.
Soil: Deep Sand & Clay Loam
Slope: Fair