T28S - R3W

Sec 27





Ditch washed out in 1922
Point of diversion moved up stream
aprox. 3/4 mile. New location 300'W, 1320'N
of S 1/4 Cor. Sec. 34 T.28S., R.3W