

For: Don Roberts/Roberts Legacy Dairy LLC

March 25th/2025

Static water levels on irrigation wells:

Buckhorn Flat West Farm:

- #1- Static water level 70'10" West 300HP Goulds Pump (same as 2024)
- #2- Static water level 69'10" 100HP Western Land Roller Pump (+2" from 2024)
- #3- Static water level 59'2" 300HP Goulds Pump (was 100HP) (-2" from 2024)

East Buckhorn Flat Lone Tree Farm:

- #1- Static water level 92'5" 300HP Floway Pump (-5" from 2024)
- #2- Static water level 113'6" 300HP Johnston Pump (+9'10" from 2024)
- #3- Static water level 132'2" 150HP Goulds Pump (was a Johnston head) (-2" from 2024)

South East Buckhorn Flat Old Roberts Farm:

- #1- Static water level 156' 200HP FM Pump (+10'4" from 2024)
- #2- Static water level 161'1" 250HP Johnston Pump (+2'11" from 2024)
- #3- Static water level 170' 300HP BJ Pump (-2" from 2024)

Paragonah Evans/Lister Farm:

- #1- Static water level 141'6" 150HP Goulds Pump (+1'2" from 2024)

Parowan Church Farm North wells:

- #1- Static water level 162' 100HP Vertiline Pump (+10'4" from 2024) this well cleaned&repaired
- #2- Static water level 147' 200HP Johnston Pump (was 150HP) (+1' from 2024) well cleaned/repair

Parowan Church Farm South wells:

- #1- Static water level 138' 100HP BJ Pump (was 75HP) (furthest East well) (+8'8" from 2024)
- #2- Static water level 129' 125HP Layne Pump (yard well) (+1'6" from 2024)
- #3- Static water level 104' 300HP Goulds Pump (west of hay barn) (-3'6" from 2024)
- #4- Static water level 101'2" 200HP Layne Pump (middle well) (+2" from 2024)
- #5- Static water level 104'10" 300HP Western Land Roller Pump (farthest west) (-10" from 2024)
- #6- Static water level 157' 100HP BJ Pump (was 75HP) (+8" from 2024)

Evens Farm:

- #1- Static water level 165'10" 300HP Johnston Pump (-2'2" from 2024)
- #2- Static water level ? Line still hangs up around 134' and will not go down further

I certify that these static water level readings were performed by Darrin Rhodes on 3/25/2025 with a Heron water level indicator and are accurate and true

Darrin Rhodes

Rhodes Pumps II LLC

Fillmore, Utah 84631

rhodespumps@frontier.com

435-979-0671